

Possible problems related to the mixing of different prepainted products

A common misconception concerning paint is that if two coatings start out the same colour, then these two coatings will be of equivalent colour throughout their service lives. Unfortunately, this is not generally the case and the purpose of this Technical Bulletin is to discuss some of the potential problems associated particularly with mixing BlueScope Steel's COLORBOND® prepainted steel with the 'same-colour' prepainted product from other sources. All of these problems relate to the development of a 'differential appearance' over time when painted products are mixed on a single installation. It should be noted that colour difference does not have to be large to be noticeable and may be quite objectionable.

DIFFERENT PAINT SYSTEMS

1. A major cause of differential appearance is the use of different pigments in two paint systems of the same colour. Close matches to a colour are often achieved with a variety of combinations of pigments and these different combinations may weather to quite different colours.

2. Another source of differential appearance is the fact that the basic organic resins used in different paint formulations will not be identical and will therefore impart different durability and properties. The difference in organic resin can lead to two problems:

- a) Coatings having different durability will show different performance in terms of gloss and colour retention and the onset of chalking. These differences will probably result in differential discolouration, which can occur rapidly or may only be apparent after long-term exposure; and
- b) In some tropical areas, e.g. South-East Asia, the different properties of the organic resins, particularly their performance at elevated ambient temperatures, may give rise to differential darkening or tropical discolouration. This effect is related to dirt retention and it can appear very rapidly.

It is therefore particularly important that COLORBOND® steel should not be mixed with another prepainted steel supplier's product on the same installation. At some

stage the colours of the different products will diverge and differential appearance will result. The use of an alternative product with possibly inferior durability will naturally exacerbate the problem. Rectification of differential appearance is a costly procedure and will at least involve over painting the entire installation.

STOCK TURNOVER

Care should also be taken if it is intended to use old COLORBOND® steel stock of the same colour as new stock. This is because the paint formulations used may have changed as part of the continuous COLORBOND® steel performance improvement program.

If you have any questions regarding this Bulletin, please contact BlueScope Steel Direct on 1800 800 789.

To ensure you have the most current Technical Bulletin, please go to bluescopesteel.com.au.

The information and advice contained in this Technical Bulletin ('Bulletin') is of a general nature only and has not been prepared with your specific needs in mind. You should always obtain specialist advice to ensure that the materials, approach and techniques referred to in this Bulletin meet your specific requirements.



BlueScope Steel Limited makes no warranty as to the accuracy, completeness or reliability of any estimates, opinions or other information contained in this Bulletin and to the maximum extent permitted by law, BlueScope Steel Limited disclaims all liability and responsibility for any loss or damage, direct or indirect, which may be suffered by any person acting in reliance on anything contained in or omitted from this Bulletin.

COLORBOND® and BlueScope and are registered trade marks of BlueScope Steel Limited.

© 2013 BlueScope Steel Limited ABN 16 000 011 058. BlueScope Steel (AIS) Pty Ltd ABN 19 000 019 625. All rights reserved.