TECHNICAL 32



MAY 2013 | Rev 1

This issue supersedes all previous issues

Impact of hail damage to COLORBOND® steel and ZINCALUME® steel roofing

INTRODUCTION

This Technical Bulletin provides a general description of the typical effects of hail stones on COLORBOND® prepainted steel and ZINCALUME® aluminium/zinc/magnesium alloy coated steel roofing.

Generally, steel roofing (minimum 0.42mm base metal thickness) is structurally robust in the event of interaction with hail stones. The roof sheeting will absorb the energy of the hail stones and remain structurally sound. However, it is possible for indentations to occur on COLORBOND® steel and ZINCALUME® steel along with loss of the paint topcoat (in the case of COLORBOND® steel).

INDENTATIONS

Generally, indentations from hail stones do not affect the life of a roof made from COLORBOND® steel or ZINCALUME® steel.

The only potential areas of concern will arise from:

- Low pitched roofs with significant hail indentations occurring within the pans leading to ponding and dirt accumulation which may promote corrosion.
- Roofs where sheet overlaps have been significantly deformed, the anticapillary effect can be lost and water could be drawn into the sheet lap resulting in corrosion.

In the event of ponding due to indentations or damage to sheet overlaps, the affected sheets should be replaced as soon as practicable to maintain the life of the roof.

Loss of the paint topcoat from the COLORBOND® steel surface, arising from impact of hailstones, will be an aesthetic issue only. The loss of paint topcoat will have no appreciable effect on the corrosion performance of the COLORBOND® steel roof. As per

Technical Bulletin TB-2 Overpainting and Restoration of Exterior BlueScope Steel Products, the use of touch-up paint to repair damage or scratches to the painted surface is not recommended.

For further information regarding comparative performance of various roofing materials In regard to hail damage, please refer to <u>Sustainability Technical Bulletin STB-9</u> Extreme Weather Events, Section 7.

RELATED BLUESCOPE STEEL TECHNICAL BULLETINS

Technical Bulletin TB-2

Overpainting and Restoration of Exterior BlueScope Steel Products

Sustainability Technical Bulletin STB-9
Extreme Weather Events

If you have any questions regarding this Bulletin, please contact BlueScope Steel Direct on 1800 800 789. To ensure you have the most current Technical Bulletin, please go to bluescopesteel.com.au.

The information and advice contained in this Technical Bulletin ('Bulletin') is of a general nature only and has not been prepared with your specific needs in mind. You should always obtain specialist advice to ensure that the materials, approach and techniques referred to in this Bulletin meet your specific requirements.

